Work Order (Bid Form)

	V	0	R	K	0	RI	DE	FR	A	=0	R	M	A	TI	0	N
-	=								 	 						

Work Order Name:

Work Order Type: Weatherization

Audit Name: HENDERSON

CLIENT INFORMATION

Client Name:

Client ID:

Alt. Client ID: 16016SW-0541

AGENCY INFORMATION

Agency: SWHRA

Address: 1574 White AVE

Henderson, TN

Agency Contact: STANFILL, BUTCH

Address:

Agency Phone: (731) 989-5111

Fax:

Email Address:

Work Phone:

Cell Phone: Email Address:

Company Name & License Number:	
Contractor's Signature:	

COMMENT

NOTICE:

All work performed and material must meet all requirements as stated in the Southeast Weatherization Field Guide. It is the contractor's responsibility to pull all necessary permits required for the town or county where the work is being performed. No change order work shall be done until the change order has been approved and signed. If heater is required no air sealing should be done before heater is installed.

731-968-3890

Client Name: Client ID:

Alt. Client ID: 16016SW-0541

Work Order (Bid Form)

Work Order Name:

Report Run On: 5/13/2010

DOE Weatherization Assistant Version 8.5.0

Page 1 of 6

Measures

	Measure 1 Infilt	tration Redctn			Component	's			Inspected
C	Comment				Ff a Africa and a selected			A . 4 i	
#	Material / Labor	Description / Comment	Units	Qty	Estimated Unit Cost	Total	Qty	Actual Unit Cost	Total
1		Seal front bedroom wall to floor pay close attention to floor at Ac	Each	1			T T T T T T T T T T T T T T T T T T T		
2	Labor	Labor	Hour						
3	Construction Materials/Hardwar e	Front bedroom seal door jam,crown molding, Kitchen pantry seal all windows and floor under sink	Each	1					
4	Labor	Labor	Hour						
5	Construction Materials/Hardwar e	Kitchen pantry seal crown molding and baseboard, Seal fuse box	Each	1					
6	Labor	Labor	Hour						
7	Construction Materials/Hardwar e	Bath Seal wall to floor,Seal crown molding and ceiling behind shower	Each	1			- Transition of the state of th	The state of the s	To the state of th
8	Labor	Labor	Hour			1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			
9	Construction Materials/Hardwar e	Seal plumbing behind washer and dryer, Dinning room seal crown molding and baseboard. Back bedroom seal inside of closet and crown molding and baseboard	Each	1		Community of the Commun			
10	Labor	Labor	Hour						
11	Construction Materials/Hardwar e	Rehang D2. weather- strip D1,D2 and D3	Each	1	AMERICAN AND AMERI	Y			
12	Labor	Labor	Hour			The state of the s			
13	Construction Materials/Hardwar e	Caulk all windows	Each	1	1	Transcript of the Control of the Con			

Client Name:

ent Name: Work Order (E Client ID: Work Order Name

Work Order (Bid Form)

DOE Weatherization Assistant

Alt. Client ID: 16016SW-0541

Report Run On: 5/13/2010

Version 8.5.0 Page 2 of 6

14 Labor	Labor	Hour						
Other Detail		process		, ,				
			Measur	e Sub Total:] ,	Sub Total:	
Field Notes:								
	/H Pipe Insulation			Componen	ts		i	Inspected
Comment								
			ANY SAME ASSESSED SOURCE STREET OF THE	Estimated			Actual	Market (1988) Marks and Franchisch (Marks and American
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	DHW Pipe Insulation	Each	1					
2 Labor	Labor	Each	1		THE RESERVE THE PROPERTY OF TH		111111111111111111111111111111111111111	A
Other Detail					n vivin er i i i i i i i i i i i i i i i i i i	The same and the same of the s	And the second s	erry spreader this transport and the state of the state o
			Measur	e Sub Total:			Sub Total:	
Field Notes:								
								a selection. Military date
								and the state of t
								Walter a mineral and a second

Alt. Client ID: 16016SW-0541

Work Order (Bid Form)

Work Order Name: Report Run On: 5/13/2010 DOE Weatherization Assistant Version 8.5.0

Page 3 of 6

	/H Tank Insulation			Componen	ts		4000	Inspected
Comment				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Hot Water Equipment	DHW Tank Insulation	Each	1		, olar	Q.y		70147
2 Labor	Labor	Each	1	The state of the s				
Other Detail								
			-					
			Measur	e Sub Total:]	Sub Total:	
Measure 4 CO Comment	Monitor is Needed			Component	ts			Inspected
U ns / + + / + +			A CONTRACTOR OF THE STREET	Estimated		M AND COMMON TO THE PROPERTY AND COLUMN	Actual	
	Description / Comment CO monitor	<i>Units</i> Each	Qty 1	Estimated Unit Cost	Total	Qty	Actual Unit Cost	Total
Health and Safety Items					Total	Qty		Total
Health and Safety Items	CO monitor	Each	1		Total	Qty		Total
1 Health and Safety Items2 Labor	CO monitor	Each	1		Total	Qty		Total
1 Health and Safety Items2 Labor	CO monitor	Each	1		Total	Qty		Total
2 Labor	CO monitor	Each Hour	1		Total			Total

Alt. Client ID: 16016SW-0541

Work Order (Bid Form)
Work Order Name:

Report Run On: 5/13/2010

Page 4 of 6

a antinetta in 10			e a oxygen d Estimated	epletion :	sensor	Actual	
scription / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
unter FloW Direct nt 50-55 KBTU tural gas heater	Each	1			A STATE OF THE STA	The report of	
oor	Hour	1					
			parameter and the second secon		. ,		
		Measur	e Sub Total:		and data of the same of the sa	Sub Total:	
eRelief Piping Need	ed		Componen	ts			Inspecte
	ed		Componen Estimated			Actual	Inspecte
eRelief Piping Need	ed <i>Unit</i> s	Qty	·		Qty		
			Estimated		Qty	Actual	Inspecte Total
scription / Comment	Units	Qty	Estimated		Qty	Actual	
scription / Comment ssure relief piping	<i>Units</i> Each		Estimated		Qty	Actual	
scription / Comment ssure relief piping	<i>Units</i> Each		Estimated		Qty	Actual	
scription / Comment ssure relief piping	<i>Units</i> Each		Estimated		Qty	Actual	Inspecte Total
		or Hour	or Hour 1		or Hour 1	or Hour 1	or Hour 1

Alt. Client ID: 16016SW-0541

Report Run On: 5/13/2010

Version 8.5.0 Page 5 of 6

	Measure 7	_	or Barrier Needed ement/Crawlspace)			Componen	ts		I	nspected
C	Comment									
					AND AND THE TRANSPORT OF THE PERSON	Estimated			Actual	
#	Material / Lab	or	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items		Basement / crawlspace vapor barrier	Each	1	The state of the s				
2	Labor		Labor	Hour	1					
(Other Detail							~;		
					Measur	e Sub Total:		v common man and a comm	Sub Total:	
New research to the second party of the second management persons of the second party and the	Field Notes:									
				Work Or	der Gra	nd Total:		Gran	d Total:	

Alt. Client ID: 16016SW-0541

Work Order (Bid Form)

Work Order Name: Report Run On: 5/13/2010

Page 6 of 6